No. 47, 18th Aliey, Ahmad Ghasir (Bucharest) Ave, Argentina Sq., Tehran, Iran

P.O. Box: 14155-4999 Tel: (+98-21) 88736554 Fax: (+98-21) 88731808





INSPECTION REPORT NO.: 650201/01479

In pursuance to an order for inspection given to us by our:

PRINCIPAL : JEY KIMIA BITUMEN
TO INSPECT (SAID TO BE) : BITUMEN GRADE 60/70

AT : JASK GOSTAR WAREHOUSE, SHAHEID RAJÄEE PORT, BANDAR

ABBAS, IRAN

ON : 25 ~ 29.01.2021

Required inspection:

- Visual checking of the packing and marking of cargo & drum dimension check at random & to report,
- Random sampling of the cargo & sending the sample to third-party laboratory for testing,
- > Visual checking of drums,
- > Stuffing supervision.

We hereby report the followings

Marking

Following markings were observed on body and top side of drums:

Type 1, painted marking:

BITUMEN 60/70

PLE BE

The commodity was poured in the new metal drums with black appearance. Each drum had a lid in the top side. Amongst the inspected drums following figures was obtained for their dimensions:

Sampling.

Sampling was performed during cargo stuffing into the containers at the warehouse from 15 number randomly selected drums. The number of selected drums is according to ASTM D 140. But only the top side of the grums were accessible for taking increment. All drawn samples were mixed as well and prepared 4.1 lifter composite samples were distributed as follows:

- One litter composite sample was dispatched to third-party laboratory with SGS seal No. 701973.
- Three x1 litter composite sample was retained in SGS for 90 days with SGS seal Nos. 701974, 701975 & 701976.

Analysis:

One composite sample was sent to non-SGS laboratory for the following items to be tested. The following specifications and test methods were reported by the lab:

SPECIFICATION	RESULTS	Standard Range		TEST METHOD
		MIN	MAX	1E31 METHOD
PENETRATION @ 25 CHO MM TO SHEET PROPERTY OF THE PENETRAL PROPERTY OF T	56565656 65	60	70	ASTM D5
SOFTENING POINT (R.A. B) PC	18G865G 50 8 G8G8G8G	46	400	ASTM D36
BERNALD LIE LO 253C SCMAIN CHARRES	100 305 P	100	Jacob 1	ASTM D 113
SPOT TEST, NAPHTA	NEG	Neg	jative	AASHTO 102
FLASH POINT, °C	336	232		ASTM D92
SOLUBILITY IN TCE, %WT	99.9	99.0		ASTM D2042
DENSITY @ 25°C kg/m3	1011.8	1010	1060	ASTM D70
LOSS ON HEATING, WT%	0.002	44.04	0.2	ASTM D6
DROP IN PENETRATION AFTER HEATING %	4.61		20	ASTM D6&5
VISCOSITY AT 135°C, CST	334	300		ASTM D2170
VISCOSITY AT 60°C, poise	1766	1600	2000	ASTM D2170

These findings are reported herein for convenience only and SGS has no liability for the subcontracted results, which remain with the lab.

Cont.2

This document is issued, on the Client's behalf, by the Company under its General Conditions of Service printed overleaf. The Client's attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Clients instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents.

Minerals Division

SGSPAPER 20414495







Inspection Report No.: 650201/01479
Page 2-of-3

Stuffing Supervision:

25 x 20' containers were ready to be stuffed under SGS inspectors' supervision at stuffing site in Bandar Abbas port. The cargo was discharged from trailers and stuffed by means of forklift in two tiers totally 110 drums in each container and the containers were sealed with SGS seals as follows:

No.	Container No.	QTY. of drums	SGS seal	Stuffing date
1	5 TTNU 148033 0 0 5	110 Drums	485216	25.01.2021
2	A PCU 313017-93555	SGSG TO A CHESS SGS TO SGSG TO	485217	25.01.2021
3	WHILU 276759-2		6565676567656765676865676567656567656765	25.01.2021
	MTU 308218-5	410 Drums	650565656565656565656565656565656565656	25.01.2021
		sesual O. Drums	485220	25.01.2021
4.11			486321	25.01,2021
	SGATU 048968-9	See 70 Drums	486322	25.01.2021
GSU-GSU- GSU-GSU- GSU-GSGSU-	ENGU 375878.7	sas 110 Drums	486323	25.01. 2021
GSG GSF G	565 TTNU 219008-4	\$656 10 Drums	486324	25.01.2021
10	TTNU 386369-9	110 Drums	486325	25.01.2021
SGSLAY SGSLASSIAN SGSGSSASSIAN	CLHU 333673 1	110 Drums	486326	25.01.2021
sc 12	TCKU 345884 7	410 Drums	486327	25, 26.01.2021
SG 13	APZU 306804-5	110 Drums	486328	26.01.2021
14	CCLU 269617-9	ass 110 Drums	· 486329	26.01.2021
15	WHLU 290409-7	cs 110 Drums	486330	26.01.2021
16	TDRU 271909-0	110 Drums	486331	26.01.2021
17	TTNU 301054-6	110 Drums	486332	26.01.2021
18	TCKU 191595-0	110 Drums	486333	26.01.2021
19	FCIU 401446-6	110 Drums	486334	26.01.2021
20	TDRU 272764-4	110 Drums	486335	26.01.2021
21.26 2515656	STEKU 280127.3	see Hubrums	486336	27.01.2021
365 5 5656 565 5 5656			\$ 486338	27.01.2021
			486339	27.01.2021
24	IPXU 365636-9	110 Drums	486550	27, 29.01.2021
25	TDRU 302815-3	110 Drums	486340	28.01.2021



SGS Iran Limited
Minerals Division

This document is issued, on the Client's behalf, by the Company under its General Conditions of Service printed overleaf. The Client's attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Clients instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents.

SGSPAPER 20414496







Inspection Report No.: 650201/01479

Page 3 of 3

Quantity:

Total stuffed containers 25 Containers Total Number of drums 2,750 Drums

Notes:

- The floor of nominated empty container was covered by a layer P-E sheet.

- About 10 ~ 15 % of drums were suffered with slightly dent on bodies by forklift. (This due to the loading method performed by the man-power and machine forklift, which the drums were in the sound condition in an appearance before stuffing into containers).

- The top side & bodies of about 21% of the drums were found slightly dirtied by due t.

"This document is issued by the Company under its General Conditions of Service printed overleaf. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained thereon reflects the Company's findings at the time of its instructions, if any. The Company's sole responsibility is to its Client and this document loss not expressed parties to a managetion from exercising all their rights and obligations under the transaction document loss not expressed alteration forgery or faisification of the content or appearance of this document is unlawful and provided and provided alteration, forgery or faisification of the content or appearance of this document is unlawful and provided and provided alteration, forgery or faisification of the content or appearance of this document is unlawful and provided and provided alteration of the law."

SGS Tehrati/Feb 016, 2021

21-90482L02

GS Iran Limited

Minerals Division



This document is issued, on the Client's behalf, by the Company under its General Conditions of Service printed overleaf. The Client's attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any other holder of this decument is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Clients instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents.



