No. 47, 18th Alley, Ahmad Ghasir (Bucharest) Ave, Argentina Sq., Tehran, Iran

P.O. Box: 14155-4999 Tel: (+98-21) 88736554 Fax: (+98-21) 88731808





INSPECTION REPORT NO.: 650201/01478

In pursuance to an order for inspection given to us by our:

PRINCIPAL : JEY KIMIA BITUMEN

TO INSPECT (SAID TO BE) : BITUMEN VG30

: JASK GOSTAR WAREHOUSE, SHAHEID RAJAEE PORT, BANDAR

ABBAS, IRAN

ON : 17 ~ 21.01.2021

Required inspection:

- > Visual checking of the packing and marking of cargo & drum dimension check at random & to report,
- Random sampling of the cargo sending the sample to third-party laboratory for testing,
- > Wisual checking of drums,
- Stuffing supervision.

We hereby report the followings:

Marking.

AT

Following markings were observed on body and top side of drums:

Type 1 painter marking

BITUMEN GRADE VG30

Packing

The commodity was poured in the new metal drums with black appearance. Each drum had a lid in the top side. Amongs the inspected drums, following figures was obtained for their dimensions:

Helphy of the course of the co

Sampline

Sampling was performed during cargo stuffing into the containers at the warehouse from 15 number randomly selected drums. The number of selected drums is according to ASTM D 140. But only the top side of the drums were accessible for taking increment. All drawn samples were mixed as well and prepared 4x1 litter composite samples were distributed as follows:

- One x1 litter composite sample was dispatched to a third-party laboratory with SGS seal No. 701820.
- Three x1 litter composite sample was retained in SGS for 90 days with SGS seal Nos. 701821, 701822 & 701823.

Analysis:

One composite sample was sent to non-SGS laboratory for the following items to be tested. The following specifications and test methods were reported by the lab:

SPECIFICATION ESCASAGES CAUSES	SEPESULTS	Standard Range		TEST METHOD
		MIN	MAX	1EST METHOD
THE REPORT OF STATE OF THE WARRENCE	SGSGSGSG GGGSGSGS	50	70	ASTM D5
PROPERTY OF THE PROPERTY OF TH	SGSGSGF 2 4 GSGSGSF	47	B.zv	ASTM D36
SUPPLIES OF THE POINT, COMPANY	330	220	Merchanapher!	ASTM D92
SOLUBILITY IN TCE, %WT	99.9	99.0		ASTM D2042
VISCOSITY AT 135°C, CST	478	350		ASTM D2170
ABSOLUTE VISCOSITY @ 60 °C, poise	2718	2400	410	ASTM D2170
AFTER THIN FILM O	VEN TEST(TF	OT), ASTM D1	754	
SPECIFIC GRAVITY AT 25 °C'	1.0214	0.99		ASTM D70
DUCTILITY AT 25°C, cm, 5cm/min	85	40	es 10-10	ASTM D113
VISCOSITY RATIO AT 60°C	2.31	400	4.0	ASTM D2171

These findings are reported herein for convenience only and SGS has no liability for the subcontracted results, which remain with the lab.

Cont.2

This document is issued, on the Client's behalf, by the Company under its General Conditions of Service printed overleaf.

The Client's attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Clients instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents.

SGS Iran Limited
Minerals Division

SGSPAPE) 20414497







Inspection Report No.: 650201/01478

Page 2 0 3

Stuffing Supervision:

 $25 \times 20^{\circ}$ containers were ready to be stuffed under SGS inspectors' supervision at stuffing site in Bandar Abbas port. The cargo was discharged from trailers and stuffed by means of forklift in two tiers; totally

No.	Container No.	QTY. of drums	SGS seal	Stuffing date
1	TLLU 294997-0	Sussilia Drums	483598	17.01.2021
2	BSIU 316605-5	GSGSGS 140 Drums	483599,465650505	17,01.2021
3	TCKU 261096-0	650505110 Drums 505050	65656565654 836	17.01.2021
4	BSIU 324239-2	cscscs 40 Drums sessor	G5656565654837446565656565656565656565656565656565656	17.01.2021
5	TCKU 164972-0	650565 Drums	483742	17.01.2021
6	TCKU 282101-1	GSGSGS 10 Drums	483743	18.01.2021
7 50	2017TNU(303105-0333	Sissa 110 Drums	483744	18.01.2021
8	10 CAIL 326293 7 65 65 65 65 65 65 65 65 65 65 65 65 65	656ats 110 Drums	483745	18.01,2021
S D GSGS	16505 16505 BBIU 284842 2 15565	SSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSSS	483746	18.01.2021
10	TCKU 365832-0	110 Drums	483747	18.01.2021
Ses S	CAIU 312133-2	110 Drums	483748	18.01.2021
12	PMLU 204861-0	140 Drums	483749	18.01.2021
13	TLLU 295015-9	110 Drums	483750	18.01.2021
14	BSIU 316304-0	asi 10 Drums	483751	18.01.2021
15	TCKU 137682-1	65/10 Drums 56	483752	18.01.2021
16	TCKU 333233-4	110 Drums	485201-485202	18, 20.01.202
17	TLLU 260897-4	110 Drums	483753	18.01.2021
18	BSIU 315042-3	110 Drums	483754	18.01.2021
19	GIPU 207273-6	110 Drums	483755	18, 19.01.202
20	TRIU 300753-1	110 Drums	483756	19.01.2021
21.55	1050 RHU 233786 10 5650	acsessi 40 Orums	483757	19.01.2021
22	SS CKU 1936726		483758 483758	19.01.2021
23	BSIU 324295-7	00000000000000000000000000000000000000	G 65P 483759	20.01.2021
24	CAOU 207552-4	110 Drums	483760 20, 21.01.202	
25	TCKU 187482-4	110 Drums	485206	21.01.2021



SGS Iran Limited Minerals Division

This document is issued, on the Client's behalf, by the Company under its General Conditions of Service printed overleaf. The Client's attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Clients instructions, if any. The Company's sole responsibility is to its Client and this document does not exonarate parties to a transaction from exercising all their rights and obligations under the transaction documents.

SGSPAPER 20414493







Inspection Report No.: 650201/01478

Page 3 of 3

Quantity:

25 Containers Total stuffed containers Total Number of drums 2,750 Drums

-Item No.16: The doors of container were not closed completely due to WH problem and or some defection on the doors. So, the mantioned container was sealed with 2 connected seals.

- The floor of nominated empty container was covered by a layer P-E sheet.
- The top side of about \$7, of the stuffed drums were found alightly direct and the bottom side of about \$7, of the stuffed drums were found alightly direct and the bottom side of about \$7, of the stuffed drums were found alightly direct and the bottom side of about \$7, of the stuffed drums were found alightly direct and the bottom side of about \$7, of the stuffed drums were found alightly direct and the bottom side of about \$7, of the stuffed drums were found alightly direct and the bottom side of about \$7, of the stuffed drums were found alightly direct and the bottom side of about \$7, of the stuffed drums were found alightly direct and the bottom side of about \$7, of the stuffed drums were found alightly direct and the bottom side of about \$7, of the stuffed drums were found alightly direct and the bottom side of about \$7, of the stuffed drums were found alightly direct and the bottom side of the stuffed drums were found alightly direct and the bottom side of the stuffed drums were found alightly direct and the bottom side of the stuffed drums were found alightly direct and the bottom side of the stuffed drums were found alightly direct and the bottom side of the stuffed drums were successful to the stuff drums were successful to th

Basticahen of the of some of containers was diffine by forklift tire and/or labora shoes.

"This document is issued by the Company under its General Conditions of Service printed overleaf. Attention is drawn to the limitation of liability inflamination and jurisdiction is used the difference of liability in the limit of the limits of Client's instructions of any of the limit of the limits of the limit of limit of the limit of the limit of the limit of the limit of the

G 3 ehran/Jen 27th, 2021 21-00303L02

Minerals Division



This document is issued, on the Client's behalf, by the Company under its General Conditions of Service printed overlast. The Client's attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Clients instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents.



